



# **Release Note**

**Software Version:** 2.2.1

Models: X5S/X6/X210/X210i/X7/X7C/X4U/X5U/X6U

Date: 2020.7.02



# Content

| Content            |   |
|--------------------|---|
| 1 Revise History   | 3 |
| 2 Release 2.2.1    | 4 |
| 2.1 New Features   | 4 |
| 2.2 Optimization   | 4 |
| 2.3 Bug Fix        |   |
| 3 Release 2.0.5    | 6 |
| 3.1 Optimization   | 6 |
| <b>3.2</b> Bug Fix | 6 |
| 4 Release 2.0.2    | 7 |
| 4.1 New Features   | 7 |
| 4.2 Optimization   | 8 |
| <b>4.3</b> Bug Fix | 9 |



# 1 Revise History

| No. | Version | Release Time |
|-----|---------|--------------|
| 1   | 2.0.2   | 2020.3.31    |
| 2   | 2.0.5   | 2020.5.12    |
| 3   | 2.2.1   | 2020.7.02    |
|     |         |              |
|     |         |              |
|     |         |              |
|     |         |              |
|     |         |              |
|     |         |              |
|     |         |              |
|     |         |              |



### 2 Release 2.2.1

| Models                   | Software<br>Version | Comment |
|--------------------------|---------------------|---------|
| X5S/X6/X210/X210i/X7/X7C | 2.2.1               |         |
| /X4U/X5U/X6U             |                     |         |

#### 2.1 New Features

- 1. The webpage supports Bluetooth function
- 2. Add default password modification prompt on Webpage
- 3. Sidekey display area can be set to three lengths of short, medium and long
- 4. Add the function of setting different forwarding numbers through one DSSKEY and one key

# 2.2 Optimization

- 1. Improve the situation that the upgraded prompt message can be chosen to display
- 2. Add the Web page configuration to control time/date display
- 3. Optimize LDAP related content

## 2.3 Bug Fix

1. Fix the problem that the line light does not turn on after restarting the phone



- 2. Fixed the issue that the name of the cloud phonebook is long and the number overlaps when it is displayed
- 3. Fixed the issue that the webpage prompts error when the two multicasts are switched the order
- 4. Fixed the problem that when the subscribed BLF has multiple incoming calls, the test phone will only displays the pick up of the first call
- 5. Fix the problem that the dhcp option deployment phone will not download the files automatically
- 6. Fix the problem that there is no prompt to hang up the peer when attending the transfer



### 3 Release 2.0.5

| Models                   | Software<br>Version | Comment |
|--------------------------|---------------------|---------|
| X5S/X6/X210/X210i/X7/X7C | 2.0.5               |         |
| /X4U/X5U/X6U             |                     |         |

# 3.1 Optimization

Compatible with uaCSTA function of Yeastar server

# 3.2 Bug Fix

There is a problem with the call record after resetting the device



#### 4 Release 2.0.2

| Models                   | Software<br>Version | Comment |
|--------------------------|---------------------|---------|
| X5S/X6/X210/X210i/X7/X7C | 2.0.2               |         |
| /X4U/X5U/X6U             |                     |         |

#### 4.1 New Features

- 5. Add the function to customize UI colors
- 6. Add the function to preview peer-to-peer SIP video
- 7. Add the function to dynamic multicast
- 8. Add the language of Portuguese
- 9. Add the function to cancel Hold automatically once the current line changes
- 10. Add the function to achieve one-click Call Park / Retrieve by setting BLF list key
- 11. LCD side screen supports displaying the pushed XML message
- 12. Support sending Active URI by SIP Notify
- 13. Add the log output interface of WLAN on web page



#### 4.2 Optimization

- 1. Improve the handling when IP Phones receive multi-channel Intercom
- 2. Support fuzzy matching for Contact search
- 3. Display the source for web pages time
- 4. Newly add the parameters, such as backup server, LAN VLAN and etc, to TR069
- 5. Add the related functions of HTTP API
- 6. X210i hotspot extension management supports displaying extension information and modifying grouping functions
- 7. Support sending VLAN ID in character string format under DHCP protocol
- 8. Improve the function that calling out with "a prefix+BLF"
- 9. Improve the default value of TLS version as 1.2



#### 4.3 Bug Fix

- Fix the issue of the phone memory leak caused by the situation that uaCSTA creates sessions for many times
- 2. Fix the issue of redirection deployment failure after the phone is reset
- 3. Fix the issue that there is no "Abc" in the input method when entering name or other text in contact column
- 4. Fix the compatibility issue of IE browser
- 5. Fix the issue of abnormal display when importing phone book in csv format
- 6. Fix the issue that the phone restarts abnormally when you establish a second call during a call by the 3CX server webclient
- 7. Fix the issue that the called party fails to hold after two extensions establish a call when they work as hotspots
- 8. Fix the issue that the pickup code is displayed in the call log after the call was picked up by calling the pickup code
- 9. Fix the issue that the configuration is still there even having cleared the configuration and then restart the phone in some cases
- 10. Fix the issue that the image is stuck in the phone answer interface when previewing video
- 11. Fix the issue that the multicast does not work when initiated by DSS key
- 12. Fix the issue that there is wrong info message when using uaCsta to call a nonexistent number
- 13. Fix the issue of the abnormal display for call logs when there is a special field of phone-context
- 14. Fix the issue that when ptime is 10, the phone will try to send 4 registration messages when registering