

Fanvil

Fanvil

Release Note

Software Version: 2.4.0.5486

Models: X3S、X4、S4、S2、X1、H3、H5、H2S

Date: 2018.03.15

1 New Features

1. Added the feature of call log search
2. Added the feature of TLS mutual authentication
3. Added the feature of French signaling tone
4. Added the DSS-key type of URL application
5. Added the feature of LAN port 802.1p priority settings
6. Added the feature of upgrading MMISSET from webpage (WEB file or Font file)

2 Optimization

1. Optimized the feature of that phone will display text prompt to indicate the reason of busy
2. Optimized the feature of the X1/X4 speech parameters
3. Optimized the feature of network phonebook can search by different SIP lines
4. Optimized the feature of that when the handset is not onhook, the phone shows prompt message
5. Optimized the feature of that after the failure of the Conference, the phone resume call automatically
6. Optimized the feature of that the same server between different SIP lines allows to transfer
7. Optimized the feature of TR-069
8. Optimized the feature of that after the phone enables attended transfer on Conference Onhook, the call will attended transfer when press the end key in conference.
9. Optimized the feature of that when attended transfer ,banned transfers call to a forbid number
10. Optimized the feature of that checking the logic of system time before TLS connection
11. Optimized the feature of VAD to disabled by default
12. Optimized the feature of SIP , supported the reason field
13. Optimize the feature of robust processing when SIP branch does not exist
14. Optimized the feature of SIP Presence compatibility
15. Optimized the feature of SIP codec negotiation ,supporting G722/16000 format
16. Optimized the feature of that SIP supports Multiple Authentication or Multiple Proxy Authentication
17. Optimized the feature of Auto Provision

18. Optimized the feature of processing logic when BLF binding multiplex calls
19. Optimized the feature of that WEB language and LCD language supports to independent Settings
20. Optimized the feature of SIP data packet receiving processing mechanism, can handle long-length SIP packets

3 Bug fixes

1. Fixed the issue that when using EHS headset and dialling number quickly the phone will be blocked
2. Fixed the issue that the phone cannot adjust volume when Call Waiting
3. Fixed the issue that the number exists but can't be searched sometimes
4. Fixed the issue that Dial Plan rules does not take effect when dialling number in transfer call
5. Fixed the issue about TR-069
6. Fixed the issue that the server send to NOTIFY reboot to phone,the phone reboot without reply 200 OK
7. Fixed the issue that the letters of Ukraine € can't display on the phone normally
8. Fixed the issue that the call holding ,the other side sends RTP ,the phone still receiving and playing it.
9. Fixed the issue that pressing the speaker , the lamp of speaker not turned off after time out
10. Fixed the issue that the phone screensaver cannot display AM/PM in 12-hour system
11. Fixed the issue that dialling number cannot wakeup the screen sometimes when open screen saver and keylock at the sametime
12. Fixed the issue that When the phone rings, pressing DSS Key will result in display number is empty and hang up the call
13. Fixed the issue that when hold a call there is no prompt tone
14. Fixed the issue that the phone can't make a call because of the display name has a special character when the FRC4475 was closed
15. Fixed the issue that upgrading the background image makes the phone unnormal sometimes
16. Fixed the issue that upgrading the wrong background image from webpage will


lead to a blank webpage

17. Fixed the issue that after call log was full, the phone will have an unusual problem when it reboots
18. Fixed the issue that the phone cannot receive intercom when receives multicast
19. Fixed the issue that the contact name not changed when the call was attended transfer or received attended transfer call
20. Fixed the issue that the Chinese name of LDAP phonebook displayed abnormal on the webpage
21. Fixed the issue that the countdown is not accurate when automatic call back
22. Fixed the issue that the item of Use Tel Call cannot be saved by unchecking it
23. Fixed the issue that the phone login webpage with Safari browser leads to 404 error at the first time
24. Fixed the issue that the display of side key was reverse in Arabic

4 New features description

1. Added the DSS-key type of URL application

Description: DSS type adds an Action type. The subtypes are HTTP GET and HTTP POST. When the user presses the DSS, the system initiates the HTTP Get/Post request. The webpage configuration is as follows:




The light of DSS Action URL is lighting-off by default. After send out the request, different states of light shows different results depending on the different reply. When received 200 OK shows success, the light will fast blink 3 times in green. Request failed or timeout, the light will fast blink 3 times in red.

2. Support LAN port setting independent 802.1p priority

Description: Add the 802.1p configuration item of LAN Port, and all of the packages from the LAN are set with VLAN tag and 802.1p priority when passing through the WAN Port.

Web page Settings:



Grab the sip package to view the VLAN tag as shown below:

